

POSITECTOR® DEW POINT METER (DPM)

APPLICATIONS

Measures and records climatic conditions including: Relative humidity, air temperature, surface temperature, dew point temperature and difference between surface and dew point temperatures. Ideal for surface preparation as required by ISO 8502-4.

FEATURES AND BENEFITS

SIMPLE

- All readings are constantly updated and displayed simultaneously
- No need to consult complex tables or use a slide rule calculator
- Alarms indicate when climate conditions are unsuitable for painting

DURABLE

- Solvent, acid, oil, water and dust resistant—weatherproof
- Shock-absorbing, protective rubber holster with belt clip
- Two year warranty on body AND probe

ACCURATE

- Fast response precision sensors provide accurate, repeatable readings
- Smart TrendTM indicators identify rising, falling or stable readings
- Certificate of Calibration showing traceability to NIST included
- Conforms to national and international standards including ISO and ASTM

VERSATILE

- PosiTector body accepts all PosiTector DPM, 6000, 200, RTR, SPG, SST, SHD and UTG probes easily converting from a dew point meter to a coating thickness gage, surface profile gage, soluble salt tester, shore hardness durometer or ultrasonic wall thickness gage
- Auto Log mode records environmental parameters at user selected time intervals
- High contrast LCD with backlit display



- Flip Display enables right-side-up viewing
- Uses alkaline or rechargeable batteries (built-in charger)

POWERFUL

- Every stored measurement is date and time stamped
- Screen Capture—save screen images for record keeping and review
- Sealed USB port for fast, simple connection to a PC and to supply continuous power. USB cable included.
- PosiSoft USB Drive—stored readings and graphs can be accessed using universal PC/Mac web browsers or file explorers. No software required.
- Includes PosiSoft suite of solutions for analyzing and reporting data

SELECT FROM 4 INTERCHANGEABLE PROBE STYLES

INTEGRAL PROBE (DPM)

- Measures dew point, RH, air temperature and surface temperature
- Measures dew point, RH and air temperature
- 1/2" NPT threads for insertion into tanks and pipes (max 200 psi/1.3 MPa)
- Sintered aluminum housing protects sensors

INTEGRAL PROBE WITH CABLED SURFACE TEMPERATURE SENSOR (DPMS)

- Includes the ambient temperature, surface temperature, and humidity sensors from PosiTector DPM Integral Probe plus a hot wire anemometer
- Choice of wind speed measurement units m/s, km/h, mph, ft/s, ft/m, knots
- Auto-rotating display for inverted use

CABLED PROBE WITH 1/2" NPT THREADS (DPMD)

- Measures dew point, RH and air temperature
- 1/2" NPT threads for insertion into tanks and pipes (max 200 psi/1.3 MPa)
- Sintered aluminum housing protects sensors

Conforms to ISO 8502-4, BS 7079-B4, ASTM D3276, IMO PSPC, SSPC-PA7 and US Navy NSI 009-32.



1800 190 190 www.blastone.com



SELECT STANDARD OR ADVANCED FEATURES

STANDARD MODELS

Includes ALL features as shown on left plus...

- Storage of 2,500 datasets
- Auto Log mode runs unattended on batteries for up to 50 hours or continuously via USB

ADVANCED MODELS

Includes ALL features as shown on left plus...

- Storage of 100,000 datasets in up to 1,000 batches
- NEW Enhanced Auto Log mode turns the gage off between readings for up to 8 months of battery life.
 Each reading can be uploaded to PosiSoft.net or an FTP server using WiFi. Automatically group readings into batches at daily, weekly, or monthly intervals
- User defined limits for all parameters—visible and audible warnings
- NEW Send email alerts when connected to WiFi
- Bluetooth Technology for data transfer to a mobile device running the PosiTector App or optional portable printer
- Onscreen Batch Annotation—add notes, change batch names and more with built-in QWERTY keyboard
- Store thickness, profile, environmental and wall thickness measurements in individual batches
- Wet bulb temperature can be displayed and recorded
- Trend Charts graph readings in real-time

POSITECTOR SMARTLINK™

 Wirelessly connect PosiTector DPM and DPMS probes to your smart device

For a complete comparison visit www.defelsko.com/dpm

SPECIFICATIONS					
	Range	Accuracy	Resolution		
Surface Temperature	-40°C to 80°C	± 0.5°C	0.1°C		
	80°C to 190°C	± 1.5°C	U.1 C		
	-40°F to 175°F	± 1°F	0.1°F		
	175°F to 375°F	± 3°F	U.1°F		
Air Temperature	-40°C to 80°C	± 0.5°C	0.1°C		
	-40°F to 175°F	± 1°F	0.1°F		
Humidity	0 to 100%	± 3%	0.1%		
Wind Speed	0 to 20 m/s	± 3% Full Scale	0.1 m/s		
	0 to 20 m/s		0.1 mph		
Dew Point	-60° to 80°C	± 3°C*	0.1°C		
	-76° to 175°F	± 5.4°F*	0.1°F		

For a complete comparison visit www.defelsko.com/dpm

ALL GAGES COME COMPLETE with environmental sensors, protective rubber holster with belt clip,wrist strap, 3 AAA batteries, instructions, nylon carrying case with shoulder strap (DPM/DPMA/DPMD), hard shell carrying case (DPMS), protective lens shield,Long Form Certificate of Calibration traceable to NIST, USB cable, two year warranty.

SIZE: 159 x 61 x 31 mm (6.25" x 2.4" x 1.2") **WEIGHT:** 150 g (5.3 oz.) without batteries

ORDERING GUIDE						
	DPM	DPMS	DPMA	DPMD		
Standard	DPM1	DPMS1	DPMA1	DPMD1		
Advanced	DPM3	DPMS3	DPMA3	DPMD3		
Probe Only	PRBDPM	PRBDPMS	PRBDPMA	PRBDPMD		

B3046-19